

Seneca County Department of Health
Environmental Services
31 Thurber Drive , Waterloo,, NY 13165
(315) 539 - 1945
jbates@co.seneca.ny.us

Children's Camp Inspection -- Summary Report

Operation: BABCOCK-HOVEY BSA (ID: 308212)
Facility Name: BABCOCK-HOVEY BSA
Facility Code: 49-0019 Facility Email: don.declerck@scouting.org
Facility Address: 7294 COUNTY ROAD 132 ROAD OVID, NY 14521

To the Attention of:
STEVE HOITT SENECA WATERWAYS COUNCIL, BSA
2320 BRIGHTON HENRIETTA TOWNLINE RD
ROCHESTER , NY 14623- Owner/Operator Email: don.declerck@scouting.org

Pre-op Inspection

Date: JUN 30, 2017 01:50 PM
Inspector: Julie Hoster (jhoster@co.seneca.ny.us)
Responsible Person: Howard Barnes
(email:)

Summary

Number of public health hazards found: 0
Number of public health hazards NOT corrected: 0
Number of other violations found: 3

Each item found in violation is reported below along with the code requirement.

SHOWERS, TOILETS

ITEM # 21 WAS FOUND IN VIOLATION 1 TIME(s).

All or parts of the violation item are IN violation.

Code Requirements

Showers-Provided, Constructed/Maintained, Plans Approved, Ratios, Water Temperature {7-2.9(c), 7-2.25(c)}

Inspector Findings

showers in bath house not well maintained

RECREATIONAL SAFETY

ITEM # 44 WAS FOUND IN VIOLATION 1 TIME(s).

All or parts of the violation item are IN violation.

Code Requirements

Special Waterfront Activities - Lifejackets Used; Supervision; Safety Plan; Boats Registered {7-2.11(h)}

Inspector Findings

waterfront is not yet set up; trampolines need to be anchored (according to manufacturer instructions) prior to opening of camp;

CONSTRUCTION, ELECTRICAL & FIRE SAFETY

ITEM # 55 WAS FOUND IN VIOLATION 1 TIME(s).

All or parts of the violation item are IN violation.

Code Requirements

*Exits: Unobstructed, Protected, Number, Dead Ends, Assembly Areas; Fires Reported {7-2.18(c)(1-5),
7-2.5(n)(3)}*

Inspector Findings

wooden doors to dining hall open inward with screen doors going outward; the wooden doors use large bars to secure the doors when building is not in use; eye hooks used with padlocks (unlocked) on exterior of office doors and privies

Additional Information Collected During Inspection

Comments

this is a correction of previous inspections for administrative purposes must be re sent;

pool PH 7.0
Bromine 2 ppm

END of REPORT

[Submit# 313584] BABCOCK-HOVEY BSA (ID 308212) Inspection# 1002155268